

Wipe Out

Description

When it comes to instantly reviving a room, Happilac Wipe Out takes its claim as a key enhancing tool. It is a top-quality water based paint that exhibits luxurious velvet appearance and exceptional aesthetic finish. It removes the stain efficiently and gives extraordinary water repellency properties. Find the perfect paint from this exclusive collection of eye-catching colors to play a symphony of happiness.

Recommended For

Happilac Wipe Out is recommended for all types of masonry surfaces such as brickwork, plaster and cement rendering. It is an ideal for interiors.

Features

- Acrylic based binder
- Extra velvety appearance
- Removes stains efficiently
- Gives water repellent properties
- Excellent covering and highly washable
- High color fastness pigments
- Enriched with an appealing perfume
- Exclusive color range
- Eco-friendly and non-toxic

Limitations

- Drying time may vary depending on weather and drying conditions.
- Ensure the correct primer or sealers are used.

Product Information

Tint Bases: Happilac Standard Tinters.	Binder type Acrylic based
Color Range: See appropriate shade card.	Pigment type Titanium dioxide
	Volume solids 45±2 %
	Weight solids 70±2 %
	Specific gravity 1.32±0.05
Happilac Tintolac: With Happilac Tintolac machine, get your happy color instantly from a color palette of 1000+ colors.	Odor Perfume enriched
	Viscosity ≤1 Poise
	PH slightly alkaline
	Application Roller, Spray
	Finish Matt
	Thinner Water
Certifications: VOC compliant in all regulated areas. OHSAS : 18001 ISO : 14001 ISO : 9001	Thinning As per requirement, Max 5-15%
	Dries by Evaporation, Oxidation
	Surface Dry 20-30 minutes
	Hard Dry 2-3 hours
	Recoat 1.5 – 2 Hrs
	*Drying and recoat times are temperature, humidity and film thickness dependent
Technical Help: Happilac technical team is always available to assist you in the correct use of our products.	Coverage 14-15m ² /liter/coat
	Film thickness 30-35 microns per coat
	Packing 16 ltr, 4 ltr, 1 ltr
	Storage temperature 4-33 °C

Surface Preparation and Application

Appropriate and good surface preparation significantly increases the top coat life and durability. Deploy skilled/experienced individuals for the application of paint. A few general instructions are given below:

New or Bare Surfaces

Surface to be painted must be dry, clean and free from all contamination. Remove dirt, grease and waxy material. Scuff with suitable sand paper, dust off and apply Happilac Wall Primer Sealer. Fill surface imperfections with Happilac Strong Wall Filling and let it complete dry followed by 2-3 coats of Happilac Wipe Out.

Previously Painted Surfaces

Scrape off all the loosely adherent paint from the surface with an appropriate abrasive paper. Properly clean the substrate and apply one coat of Happilac Wall Primer Sealer followed by 1-2 coats of Happilac Strong Wall Filling. Ensure the complete drying and apply 2-3 coats of Happilac Wipe Out.

Sequence	Recommended Paint System	
	Recommended Product	No. of Coats
Sealer	Happilac Wall Primer Sealer	1
Putty/Filling	Happilac Strong Wall Filling/Happilac Silk Putty	1-2
Finish	Happilac Wipe Out	2-3

Health and Safety Notes

- When applying paint, wear appropriate eye protection.
- In case of eye contact with product, rinse with plenty of water for at least 10 minutes.
- Don't breathe spray mist or dust.
- Ensure proper ventilation when applying paint.
- If swallowed, it may cause serious damage.
- When empty, don't use its container for edible storage.
- Place out of reach of the children.
- Pregnant women are advised to avoid breathing of paint mist or spray.
- In case of any emergency, undergo medical supervision as soon as possible.

CAUTION: Scraping/sanding off previously painted surfaces may release lead dust or fumes. Lead is highly toxic; take protective measures thoroughly when rubbing off the old surfaces.